

EPA DAL

MMMM

EASYLINK MBX 4992914C001 27SEP85 14:29/15:57 EST
VIA: 9108614125

TO: 62811461

EPA DAL

WU INFOMASTER 4-026343S270-002 09/27/85
ICS IPMBNGZ CSP
7137858612 DGM TDBN HOUSTON TX 157 09-27 0225P EST
TWX 9108614125 EPA DAL
1330 EPA



49
POLREP *49* SUBJECT PCB SPILL *49* BATH ELECTRICAL SERVICE INC RICHWOOD
BRAZORIA TX

ATTN, MARY ELLEN CROWLEY

SITUATION; ROLLINS HAS LOADED DIRT PILE FROM YARD INTO DUMPSTERS THE MORNING OF 9-27-85 AND ARE READY TO TRUCK CONTAMINATED SOIL TO NEVADA DUMP SITE. TWO SAMPLES WERE TAKEN IN THE YARD AT 1257 HOURS SAMPLE 38 AT HOTSPOT IN FRONT OF LEFT BROWN BUILDING AND SAMPLE 005 WHERE CONTAMINATED DIRT WAS PILED. THESE SAMPLES WERE SENT TO LAB FOR ANALYSIS. FUTURE PLANS; THE COMPANY WILL AWAIT RESULTS OF 4 SAMPLES TAKEN FROM THE DITCH EARLIER IN THE WEEK, AND RESAMPLE TWO HOT SPOTS IN DITCH WHERE RESULTS OF ANALYSIS WERE 26 AND 1600 PPM. THE TWO SAMPLES TAKEN 9-27-85 WERE SENT TO LAB FOR ANALYSIS BES PLAN TO DIG AT LEAST TWO SPOTS IN THE DITCH AND LOAD DIRT AND RESAMPLE. THEY PLAN TO REINSTALL CULVERTS IN DITCH WHICH HAS BEEN DECLARED CLEAN STARTING MONDAY SEPTEMBER 30, 1985. CASE PENDING

FRANK ONELLION

1427 EST

EPA DAL

MMMM

EASYLINK MBX 4994827C001 27SEP85 14:56/15:57 EST
VIA: 9108614125

TO: 62811461

EPA DAL

WU INFOMASTER 4-028416S270-002 09/27/85
ICS IPMBNGZ CSP

90072478

